RFE-7B-HP *Reprogramming Kit* ™

Patent Pending



Fits: RFE's 45-68 1999-2010 Gas & Diesel. All with 7-Ball Valve-Body

Prevents-Corrects-Reduces

Converter drain back.
Allows use of Pump Cover with worn TC limit bore.
HD Accumulator Cover Plate Replacement

Features: ADDS 30% More Line Pressure at all throttle openings without the need of computer software.

Perfect for Performance & Hard Worked Trucks

<u>Transmission Removal Required</u>

Please start with Separate pages: Read 1st-Part Selection, Drum Data & Important Information

Super Upgrade for the OD Clutch!



Short, Clean Shifts
That Hold The Power!

Calibration that Relearns Quickly.



New Design OD/Reverse Pressure Plate Allows:

14 single sided OD frictions (Diesel) 15 % Gain or 5 double sided OD Friction (Gas) 25 % Gain A Cost Effective Upgrade
See Drum Data in **Read 1st** pages for more info.

1/21/20

© TransGo 2019

These next two steps create a converter pressure limit system to Drill Jig shown bolted to pump cover. prevent the converter from being overcharged in lockup. Pilot Hole **Step 1.** With this valve lineup removed. Use two Pump bolts to tighten drill jig down, with the notch in the lower right hand corner as shown. Use the .093" drill go thru the jigs pilot hole & drill thru the pump cover just enough to enter the accumulator piston bore. Do Not drill out the other **side of pump cover!** Remove jig, use de-burring tool to deburr the bore. Notch **Drill Jig Mounting Holes New Ex Hole** Stroke the de-burring tool several times in bore & blow with air to ensure all chips and burrs have been removed from drilling the new Ex hole. **De-burring Tool** Reuse original divider clip CC Reg Valve & Spring Reuse **Three New plain Springs** Reuse Reuse Reuse Accum Piston Open End **New Slotted Retainer** Step 2. Reinstall original CC Reg Valve, Spring & Divider Clip. Discard the original Accum spring & Place the Three New plain Springs into open end of Accumulator Piston, install into pump cover & use the **new slotted Retainer** as shown. The above two steps creates a converter max pressure limit system when in lockup.

The above two steps creates a converter max pressure limit system when in lockup. It does not affect the apply feel of TCC. If using a Triple Disk Converter & want a smother TCC Apply, open the optional pack containing New TransGo **RFE-TCC-3D** valve & install as shown. **RFE-TCC-3D** is not needed or wanted if using a factory type twin disk converter.

Step 1.


Remove & ID which Type TC Valve the pump has: If it has **TYPE 1** Valve, use NEW **Type 1** Bushing!

Discard original TC Limit Valve, Spring & Retainer.

Install new Bushing, GOLD ball, ORANGE Spring & V-Notch retainer

It is correctly installed when the bushing is inserted far enough to install the retainer.

Now Regardless of the amount of bore wear this system works perfectly!



Please take a minute and look the pressure regulator valve over, there should be no holes drilled anywhere with a stock valve if there is, plug them or a replacement valve/pump cover will be necessary. Never use this kit with a Modified PR Valve.

Valve Body Step 1. **Aluminum** Pistons Only: Install wire expander © 7 Checkballs and new ring into inner ring groove as shown. Install 7-Balls as shown Step 2. Plastic Pistons: Skip this step. OD Accumulator: Use New Washer? Hold it! **Expander** Ring Spring White or Plain? The supplied Plate in this kit See Next Page. can only be used in a Truck That came with a 7 ball VB 1999-2010 Need a 5-Ball 2011-2018 Order Kit # RFE-5B-HP This inner spring has larger wire on 68RFE. Step 3. **Switch** End Discard original valve and Plug **Valve** plug. Install new self cleaning Switch Valve and new End Plug furnished.

Step 4. Install NEW **HD Cover** Using Loctite on the screws

OD Accumulator choices: From page 4 New Washer? Spring White or Plain?


- 1. Stock OD Drum with 12 single sided frictions (Diesel), or 4 double sided Friction (Gas): Use Plain Spring & the Washer.
- 2. Stock Drum with thinner **TransGo** p/n **RFE-PP-ODHP** OD/REV pressure plate & 14 single sided frictions (Diesel), or 5 double sided Friction (Gas): **Use White Spring & No Washer.**
- 3. After-market OD Drum with increased apply area with any friction combo: Use White Spring & No Washer.

Clutch Tips: O.E. BW **OD friction plates** & good oil minimize the chance of a *squawk* on the shift.

Clutch thickness's may vary with different manufacturers and can effect clearances especially on single sided clutches due to number of plates!

The New PR spring and matching triple separator plate adds 30% more line across the entire curve to all clutch packs and keeps the transducer circuit from seeing the increased line. Individual clutch ports is the only place to see the increase. Adding two plates to the OD clutch gains another 15% bringing the total to 45% plus in holding capacity of the OD clutch and 30% of all other clutch packs.

The new TCC Limit System on page 2 keeps the increased line from ballooning or stretching the converter.



Take time to look over the channel casting '


for any previous modifications there should be no holes drilled in the passage shown. Plug or replace casting as necessary.

Assembling Valve Body

- 1. Install 7 check balls as shown.
- 2. Smaller gasket installs first against the VB.
- 3. Next install New Triple Separator Plate.
- 4. Larger gasket on top of triple plate and lastly install the channel casting, using the factory dowels to line it all up.
- 5.Use the 15 New Longer bolts supplied for mounting solenoid body to channel.

Valve-body half's & Solenoid body **Torque** 60 IN-LB's Valve-body to case bolts 105 IN-LB's. Go around all bolts two or three times with at least 1/2 hour between torqueing's. This gives the gaskets some time to compress.

Page 5



Using Aftermarket Billet Channel Please

Both rivets in the Triple plate clear the factory castings.

Rivet #1 hits the after market billet channel. A 5/16 hole must be drilled 3/16 deep in billet channel to clear rivet # 1.

Scribe a line .220" in from the outside edge of billet. Scribe a line .480" up from the edge of the bolt hole just below the rivet hole.

Where the two lines meet drill a 5/16 hole 3/16 deep in the billet channel


Double check. Lay triple plate on to billet channel lining up dowel pin holes in the plate to billet. Checking that the plate will lay flush and the rivet head drops in to the new hole.

Future runs of the Billet Channels will come pre drilled, 3/16/19

> .480 Bolt Holé

Partial View of Billet Channel

The New Triple plate has some holes that are not in all three plates this is ok & normal. The smaller Gasket supplied has one extra hole over any other gasket out there so use the gaskets supplied with this kit.




Channel.

adding power.

Read First

Part Selection, Important Information & Drum Data

Yes, we know. It's a lot to read and yeah you could just skip it and roll the dice **BUT** before you do, understand this data is the result of some very switched on guys burning through truckloads of money in parts and labor learning what is painfully important to pay attention to and what actually works to be successful! Please read it!



Pump Checkup

High Mileage Stators can wear the bore at the TCC Accum Piston. Making a checking tool- Epoxy a 2" long bolt inside an old Accum piston to use as a handle for checking bore by feel or with a vacuum system. Don't assume its ok by Vac checking divider clip location as piston needs to be in the middle of its travel to find the leak. Worn Bore causes TCC Slip codes or 3-5 Cut-loose as the converter may not hold when ramped back to partial apply during shifts. (This becomes much more apparent with heat & added horsepower.) The point is, start with a good pump and check the wear points. Not all 200,000 mile pumps are a good candidate for HP use. .003 inch clearance across the gears is max or you'll risk low pressure, hot, at low rpm. Problem gets worse with oversized tires w/factory axle ratios as this lowers engine rpm.





VB Checkup

Pressure, time & heat induce flexing of the channel walls. This movement scrubs the separator plate leaving a mark and erodes the aluminum casting causing cross-leaks. Visible factory machining marks worn away & a dull look on top of casting webs is what you are looking out for all over both half's.

Often seen in high mileage 68RFE Diesels due to higher pressure and heat. Repeated OD Clutch failure is common.


This condition is not easily solved by surfacing the VB.

Gaskets do help if the partition walls are not worn to badly or weakened. It's a good idea for long term durability to replace the VB. 45RFE VB's have been used to replace 68RFE VB's.

Just swap over the accumulator springs, Sol Pack, Range Sensor Plate & Manual Valve on 5B models. Keep springs in order.

Using a VB over? Fix the solenoid switch valve bore.

P/N RFE-SV420-WT or RFE-SV453-WT available from your distributor.



Divider Clip Location

Important Information regarding Computer Tuning before starting.

The New TransGo Tuneless RFE kits are designed to be a standalone transmission modification used **ONLY WITH OEM-TCM** Transmission Tuning. If the truck has the DPF, EGR or CAT deletes, re-flashing the PCM back to stock is no easy task as the deleted components-systems must be reinstalled before the truck will run on a factory engine tune. Some tuners may require the program to be uninstalled & reinstalled choosing **NO** Transmission Modifications.

Verify stock line pressure commands are installed.

Line pressure values are listed below & can be used to verify the line pressure programming is at OE calibration.

Grab a scan tool and monitor desired line pressure. In the drive range make sure the actual pressure is the same or within a few pounds of desired. If the DESIRED line pressure values are higher than listed below, the ECM/TCM does not have stock trans tuning, consult the tuner for stock transmission program files! If the desired Max pressure is 170-250 PSI the software has been altered.

Checking line pressure: In drive idling, at a stop. Desired=60 PSI Briefly power brake above 1/2 throttle. Desired = 160 PSI

Driving in 5th or 6th at 50% or more throttle **Desired 160PSI.** Even if pressures are the same as listed this does not prove that the correct year calibration is installed. With this kit installed with the correct year and factory trans files there will be no clunks or bangs just clean short shifts that hold the power with nothing else to say.

If the truck has any aftermarket electronic transmission pressure enhancing devices **REMOVE THEM.**

Anytime an engine tune is flashed on a 2010 and later RAM Truck with a 68RFE, the transmission program is automatically overwritten with whatever trans program the tuner has provided, even if it was sold as an engine only tuner. The program files from almost any year Ram will install, but there can be negative side effects if a different year file is used. As of 11/2018 we have seen at least 6 distinct versions of PCM/TCM calibration, 2007-2009, 2010, 2011-2012, 2013-2016, **2017, 2018** & there maybe more.

We strongly recommend running the correct year program file for the vehicle and ONLY with unmodified transmission tables when installing this kit. Running the incorrect year program file, or poorly modified engine programs with the TransGo tuneless calibration can result in harsh shifting rough lock-up apply, shift timing and or lock-up timing issues, along with shuttle shifting & unexpected downshift complaints. The newer the truck is, the more critical this becomes. We have found no universal program file that fits all years and works correctly. If you are having trouble with one and need help with your Program Identification it can be found on the main menu of your scan tool under miscellaneous functions and PCM information. Once you have located it on your scan tool give us a call. Please note: We can only identify what year and model the file came from. We will not be able to identify what has or has not been modified.

If the aftermarket program is running "code setting suppression or limp-in mode delete", any troubles at highway speed can lead to unwanted downshifts to 2nd or 1st gear at abnormally high speed causing tire skid or parts breakage. One great function of limp-in mode is to put the trans in neutral above 35 or 40 MPH if a problem is detected and keep it there until the truck slows down to a safe enough speed. Letting a truck leave with loss of communication codes or with code suppression is risky business.

A special warning about loss of communication codes. Codes maybe stored in PCM,TCM, Instrument Cluster or ABS modules. These codes are often associated with the instrument cluster losing gear display and the UD/OD clutch hub shafts splitting, twisting or breaking.

Oversize tires without compensating axle ratio changes creates real headaches. Add a hot engine tune and you are now playing with fire. For example, With taller tires a light throttle 5-6 shift with TCC on at 50 MPH can leave the engine lugging at 1020 RPM's. The Hot tune has the load/torque tables jacked up for line pressure command only and not the shift speed. The PCM/TCM commands 160 PSI plus with the engine at 1020 RPM and the pump cannot produce 160 PSI at that RPM. The check valve in the pump now opens and you now have 2 pumps working and line PSI spikes up and the flapper closes, then line drops again because one pump still can not make 160 at 1020 RPM's. This 50 to 60 psi spike or oscillation will continue until the engine RPM is somewhere above 1300 RPM's. This can kill converter or OD clutches & flex/crack alum VB parts.

We have been involved with 100's of 68RFE trucks running around with the pump check valve removed since December of 2018. This has proven to be a big help with delivering extra volume at lower RPM's with no known side affects reported as of 7/13/2019. With the check valve removed both sides of the pump feed the trans all the time. Removing the check valve has also helped with Hot operation-Converter Clutch dragging coming to a stop.

Overheating Concerns

We have had numerous complaints on 68RFE transmissions with overheating issues. One of the causes may be a stuck cooler bypass valve. 2011 up trucks have an in-line cooler bypass to allow the fluid to bypass the cooler when the vehicle is cold. This function warms up the transmission quickly in cold weather. When the fluid temperature warms up sufficiently, the thermal valve opens up and routes fluid thru the transmission cooler. The overheating problem is a result of the valve in the thermal bypass sticking in "bypass" position and fails to route fluid thru the transmission cooler. Replacement is the best solution.

52014523AA Thermal bypass with lines 2011-12 List price \$259 68186711AB Thermal Bypass Block 2013-17 - List price \$81.70

Remember! When flushing these units the valve does not open up until the fluid gets hot.

IF cooler flow is good, the cause may be the **Viscous** Cooling Fan not coming up to the correct RPM. Example: Fan RPM on one truck was only reaching 850, it should have reached 2230 RPM with the engine RPM at 2500. Fixing the fan fixed the truck. **Note:** There were **no** engine cooling concerns while the trans was overheating.

Tip: You can control the fan with the a scanner or ground it and it should come up to 2230 Fan RPM at 2500 Engine RPM.

The Next several pages are input drum assembly diagrams and instructions for adding an extra clutch to the OD pack.

ALL MODELS: Drum ID & New Underdrive Snap Ring

Identify Your Drum First:


Input Drum--Cutaway Side View

Then turn to the page that matches both Transmission Model and Drum ID for stack-up information.


Measure from top of drum to top of .061" flat snap ring:

□ 1999-06 = 1.907" Drum I.D. □ **2007up** = 1.960"

Typical Input Drum--Cutaway Side View



Tip: Tap new snap ring into place as shown. It should be tight!



Heavy Duty Underdrive Snap Ring

Replaces tapered ring that breaks and pops out.

NEW .091 to .094" Flat **Snap Ring** provided on all models.

replaces tapered

4799097 -UD/OD Clutch Piston

Retainer (Inner Alum Drum)

All 68RFE with 1.960" Input Drum & Factory Stackup:

Heads Up! All 68RFE's UD & OD clutch friction surfaces face UP! UD clutch has ten .058" frictions.

OD clutch has twelve .050" frictions.

Reverse clutch has two double sided .075" frictions & one .068" steel. **UD stack**- Start with .058" friction plate with external lugs, alternate with internal lug plates. The stack will end with a friction plate with internal lugs. Install thin snap-ring, UD/OD Pressure plate then replace tapered snap-ring with new .091 to .094" flat snap-ring.

OD stack- Start with .050" friction plate with external lugs, alternate with internal lug plates. The stack will end with a friction plate with internal lugs. Install waved snap-ring, OD/Rev Pressure Plate *If plate has a step, (ID #'s 1 & 2) the stepped side faces down, then install flat snap-ring. Rev stack- Start with double sided friction, steel, double sided friction, Pressure plate and flat snap-ring.

OD Clearance adjustment not necessary WITH correct parts usage. (Uses OD/Rev Plate p/n 68323984AA 9.62-9.85mm)


Rev Press Plate Snap Ring is selective to adjust Rev Clearance.

UD Clearance adjustment not necessary WITH correct parts usage.

(It should already be within spec's.)

UD/OD Press Plate has approx .125" offset on OD side p/n 52119658AD

Measure OD
Side Offset
= .125"



Input Drum--Cutaway Side View

If using TransGo[®] p/n **RFE-PP-ODHP** OD/Rev Pressure Plate sold separately, go to page 5A for clutch parts stack up.

7/25/2019 Page 5 © TransGo 2019

All 68RFE with 1.960" Input Drum & Modified Stackup using New TransGo® OD/REV Plate:

Order from your distributor p/n RFE-PP-ODHP (sold separately). Makes it easy to add MORE Clutch to the OD Stack!

Heads Up! All 68RFE's UD & OD clutch friction surfaces face UP! UD clutch has ten .058" frictions.


OD clutch uses fourteen .050" frictions with NEW OD/REV pressure plate. **Reverse clutch** has two double sided .075" frictions & one .068" steel. **UD stack-** Start with .058" friction plate with external lugs, alternate with internal lug plates. The stack will end with a friction plate with internal lugs. Install thin snap-ring, UD/OD Pressure plate then replace tapered snap-ring with new .091 to .094" flat snap-ring.

OD stack- Start with .050" friction plate with external lugs, alternate with internal lug plates. The stack will end with a friction plate with internal lugs. Install waved snap-ring, **NEW OD/Rev** Pressure Plate, flat snap-ring. *New plate has a step and allows 14 single sided plates to be installed. Rev stack- Start with double sided friction, steel, double sided friction, Pressure plate and flat snap-ring.

OD Clearance adjustment usually not necessary* when using **NEW** TransGo® OD/REV Pressure Plate with suggested OD stackup. Rev Press Plate Snap Ring is selective to adjust Rev Clearance. **UD** Clearance adjustment not necessary **WITH** correct parts usage. (It should already be within spec's.)

Clutch Clearances UD .038 - .068" OD .040 - .063" Rev .032 - .049" L/R .045-.081" 4C .030-.053" 2C .038-.066"

UD/OD Press Plate has approx .125" offset on OD side p/n 52119658AD



UD Outer Lug .058" (Qty=5) **OD Outer Lug .050" (Qty=7)** REV FRICTION .075" (Qty=2) UD Inner Lug .068" (Qty=5) OD Inner Lug .050" (Qty=7) REV STEEL .068" (Qty=1)




Stepped Side Faces OD Clutch

Order **NEW** OD/REV Pressure Plate

TransGo® p/n RFE-PP-ODHP

Replaces O.E. OD/REV pressure plate. Use OD stackup suggested.

*Note: O.E. Friction tolerances are held very tightly. Other friction products may not be exactly the same thickness. **Example**-A .002 inch difference per friction on a 14 plate stackup can cause a clutch clearance issue. Always **measure** clutch clearances!



2014up 66RFE with 1.960" Input Drum & Factory Stackup:

Heads Up! 2014up 66RFE OD Clutches are thinner

& the Steels are thicker than UD and Rev.

The UD/OD & OD/Rev Pressure plates were also changed at the same time from the previous 2012 & 2013 models.

UD FRICTION .075" (Qty=4)

UD STEEL .068" (Qty=4)

Clutch Clearances
UD .030 - .063"

OD FRICTION .070" (Qty=4) OD .040 - .063" OD STEEL .120" (Qty=4) Rev .023 - .058"


REV FRICTION .075" (Qty=2) REV STEEL .068" (Qty=1) **OD** Clearance adjustment not necessary **WITH** correct parts usage. (Uses OD/Rev Plate p/n **52119929AB** 8.79-9.01mm)

Rev Press Plate Snap Ring is selective to adjust **Rev Clearance**. **UD** Clearance adjustment not necessary **WITH** correct parts usage. (It should already be within spec's.)

UD/OD Press Plate has approx .081" offset on OD side p/n 68186197AA

Measure OD





If using TransGo[®] p/n **RFE-PP-ODHP** OD/Rev Pressure Plate, sold separately, go to page 6A for clutch parts stack up.

2014up 66RFE with **1.960**" Input Drum & **Modified Stackup using New TransGo® OD/REV Plate**:

Order from your distributor p/n RFE-PP-ODHP (sold separately). Makes it easy to add 1 MORE Clutch to the OD Stack!

Heads Up! 2014up 66RFE Factory OD Clutches are thinner & the Steels are thicker than UD and Rev. The UD/OD Pressure plate was also changed from the previous 2012 & 2013 models.

To add a clutch and steel to the OD Stackup using the NEW OD/REV Pressure Plate requires changing the **OD frictions** to .075" thick and **OD Steels** to .087" Save any original OD parts for future stock repairs.

Rev .023 - .058"


OD Clearance adjustment often not necessary when using **NEW** TransGo® OD/REV Pressure Plate with suggested OD stackup. Rev Press Plate Snap Ring is selective to adjust Rev Clearance. **UD** Clearance adjustment not necessary **WITH** correct parts usage. (It should already be within spec's.)


UD FRICTION .075" (Qty=4) UD STEEL .068" (Qtv=4)

Clutch Clearances OD FRICTION .075" (Qty=5) UD .030 - .063" **OD STEEL** .087" (Qty=4) OD .040 - .063"

REV FRICTION .075" (Qty=2) **REV STEEL** .068" (Qty=1)

UD/OD Press Plate has approx .081" offset on **OD** side p/n **68186197AA**





Page 6A

ALL 45/545/65RFE & 2012-13 66RFE* with 1.960" Input Drum & Factory Stackup:

*Watch out for this: 2012-13 66RFE's may have been repaired with 2014up Input drum parts, see pg6.

Heads Up! 45/545/65RFE & 2012-2013 66RFE

OD Clutches & Steels are thicker than UD and Rev.

UD FRICTION .075" (Qty=4)
UD STEEL .068" (Qty=4) Clut

Clutch Clearances

OD FRICTION .090" (Qty=4)

UD .030 - .063" OD .043 - .065"

OD STEEL .087" (Qty=4)

Rev .023 - .058"

REV FRICTION .075" (Qty=2)

REV STEEL .068" (Qty=1)


OD Clearance adjustment not necessary **WITH** correct parts usage. (Uses OD/Rev Plate p/n **68323984AA** 9.62-9.85mm) **Rev** Press Plate Snap Ring is selective to adjust **Rev Clearance. UD** Clearance adjustment not necessary **WITH** correct parts usage.

UD/OD Press Plate has approx .065" offset on OD side p/n 68009902AC

Measure OD



(It should already be within spec's.)



If using TransGo[®] p/n **RFE-PP-ODHP** OD/Rev Pressure Plate, sold separately, go to page 7A for clutch parts stack up.

ALL 45/545/65RFE & 2012-13 66RFE* with 1.960" Input Drum & Modified Stackup using New TransGo® OD/REV Plate: Order from your distributor p/n RFE-PP-ODHP (sold separately). Makes it easy to add 1 MORE Clutch to the OD Stack!

*Watch out for this: 2012-13 66RFE's may have been repaired with 2014up Input drum parts, see page 6

Heads Up! 45/545/65RFE & 2012-2013 66RFE Use this modified stackup if you purchased the NEW TransGo® Pressure Plate: p/n RFE-PP-ODHP The first 2 frictions of the OD stack must be .090" thick!

UD FRICTION .075" (Qty=4)
UD STEEL .068" (Qty=4)

OD FRICTION .090" (Qty=2)
OD FRICTION .075" (Qty=3)
OD STEEL .087" (Qty=4)

REV FRICTION .075" (Qty=2)
REV STEEL .068" (Qty=1)


Clutch Clearances
UD .030 - .063"
OD .043 - .065"
Rev .023 - .058"

OD Clearance adjustment often not necessary when using NEW TransGo® OD/REV Pressure Plate with suggested OD stackup.
Rev Press Plate Snap Ring is selective to adjust Rev Clearance.
UD Clearance adjustment not necessary WITH correct parts usage. (It should already be within spec's.)

UD/OD Press Plate has approx .065" offset on OD side p/n 68009902AC

Side Offset
et = .065"

Measure OD



ALL 45/545 1999-2006 with 1.907" Input Drum & Factory Stackup:

Heads Up! 1999-06 Trans's may have been repaired with 2007up Input drums. Measure drum first to ID. Use a stackup that agrees with your drum and UD/OD plate measurements!

UD FRICTION .075" (Qty=4)
UD STEEL .068" (Qty=4)

Clutch Clearances

OD FRICTION .090" (Qty=4)


OD STEEL .087" (Qty=4)

REV FRICTION .075" (Qty=2)

REV STEEL .068" (Qty=1)

OD Clearance adjustment not necessary **WITH** correct parts usage. (Uses OD/Rev Plate p/n **04799116AB** 9.62-9.85mm) **Rev** Press Plate Snap Ring is selective to adjust **Rev Clearance. UD** Clearance adjustment not necessary **WITH** correct parts usage. (It should already be within spec's.)

UD/OD Press Plate has approx .021" offset on OD side p/n 04799107AB (supersedes p/n 68009108AA)



Measure OD
Side Offset
= .021"

If using TransGo[®] p/n **RFE-PP-ODHP** OD/Rev Pressure Plate, sold separately, go to page 8A for clutch parts stack up.

ALL 45/545 1999-2006 with 1.907" Input Drum & Modified Stackup using New TransGo® OD/REV Plate:

Order from your distributor p/n RFE-PP-ODHP (sold separately). Makes it easy to add 1 MORE Clutch to the OD Stack!

Heads Up! 1999-06 Trans's may have been repaired with 2007up Input drums. Measure drum first to ID.

45/545RFE 1999-06

Use this modified stackup if you purchased the **NEW** TransGo® Pressure Plate: p/n RFE-PP-ODHP The first friction of the OD stack must be .090" thick!

UD FRICTION .075" (Qty=4) .068" (Qty=4) **UD STEEL**


Clutch Clearances OD FRICTION .090" (Qtv=1) UD .030 - .063" OD FRICTION .075" (Qty=4) OD .043 - .065" **OD STEEL** .087" (Qty=4) Rev .023 - .058"

REV FRICTION .075" (Qty=2) .068" (Qty=1) **REV STEEL**

Installs Here!

OD Clearance adjustment often not necessary when using our p/n **RFE-PP-ODHP** OD/REV Pressure Plate with suggested OD stackup. **Rev** Press Plate Snap Ring is selective to adjust **Rev Clearance**. **UD** Clearance adjustment not necessary **WITH** correct parts usage. (It should already be within spec's.)


UD/OD Press Plate has approx .021" offset on OD side p/n 04799107AB (68009108AA)



Measure OD

NEW OD/REV Pressure Plate

An easy way to add an **Extra Clutch** to the OD!



Input Drum--Cutaway Side View