JF010E-SPR (Secondary Pulley Regulator Valve)

Corrects / Prevent / Reduces Trouble Code P0868 - Secondary Pulley Pressure too Low. Trouble Code P0730 - Incorrect Gear Ratio.

Fits: Nissan JF010E / RE0F09A	/ В
07-12 Altima 3.5L	
07-15 Maxima 3.5L	
02-16 Murano 3.5L	
10-16 Quest 3.5L	



Step 1. Discard original SPR Valve and spring. Clean the **New SPR Valve** provided and test fit it into the clean VB bore. If it moves freely, remove it and put a small dab of assembly gel into the groove of the new valve followed by the **NEW Scarf Cut Ring.** Now roll the new **O-ring** provided on top of the scarf cut ring and place it in the freezer for 15 minutes. This will "size" the ring into the groove. **Note:** The O-ring is only used as a sizing tool.



Step 2. To install, roll the O-ring **off** the valve and set it aside. Insert the **NEW White Spring** into the hollow end of the new valve and insert new valve and spring into the bore while it's still cold, followed by the original End Plug & Retainer. It will go right in **IF** the outer diameter of the ring is flush with the new valve. Never force the valve into the bore. Once you install the valve and ring– **DO NOT REMOVE THEM!**









© TransGo 2020

Next 3 Pages are VB data

JF010E Valve Body Data





Lower VB Plate



JF010E Valve Body Data



[©] TransGo 2020

